


Index No. V1

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 54H Coordinates: X _____ Y _____
NW 31 Corner common to sections 30,31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Species	Bearing	Trees	
<u>B. Oak</u>	<u>B. Oak</u>	<u>W. Pine</u>	<u>B. OAK</u>
<u>8"</u>	<u>8"</u>	<u>8"</u>	<u>8"</u>
<u>S65E</u>	<u>S16W</u>	<u>N60E</u>	<u>N20W</u>
<u>36LS</u>	<u>23LS</u>	<u>40LS</u>	<u>36LS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HORST
Location filed COUNTY RESURVEY PLAT "E-54", "E-55"
Monument IRON MONUMENT
1921, E. B. HORST, BOOK "E" P. 445 FND 2 1/2 x 48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1984 By Tony Kerick
Corner Certificate
Fnd 3" brass cap set in 1958 by Harold Curo

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>5"</u>	<u>S48E</u>	<u>17.45'</u>
<u>Maple</u>	<u>6"</u>	<u>S27W</u>	<u>26.90'</u>
<u>Maple</u>	<u>10"</u>	<u>N21E</u>	<u>29.98'</u>
<u>Maple</u>	<u>7"</u>	<u>N64W</u>	<u>18.87'</u>

↑ 1958 trees remarked ↑

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - HAROLD CURO - 1958
Certificate - Tony Kerick - 1984
Doc. # 280488

Re monumentation certificate prepared _____ By _____
Filed at _____ Date _____