


Index No. X 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
C 14 Corner common to sections 34



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER
Location filed _____
Monument Found 1 1/2" iron pipe. Set 6" x 5' cylindrical concrete monument with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search NOV. 2000 By CCSO
Find. in place; concrete monument w/ brass cap, 1962 - RLS 3628. Found 2" IP on so. side of monument, up 1.6'. Located 60' E W of E.C.R. 71.

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>Oak</u>	<u>Cedar Post</u>
Diameter	<u>13"</u>	<u>8"</u>	<u>4x4x72"</u>
Bearing	<u>S 71 W</u>	<u>N 49 E</u>	<u>S 3 1/2 E</u>
Distance	<u>91.05'</u>	<u>8.1'</u>	<u>2.1'</u>

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>R. Oak</u>	<u>R. Oak clump</u>	<u>USFS Post</u>
<u>4"</u>	<u>6"</u>	<u>12"</u>	
<u>N 88° W</u>	<u>S 8° E</u>	<u>N 54° E</u>	<u>NORTH</u>
<u>9.78'</u>	<u>32.87'</u>	<u>7.87'</u>	<u>2.7'</u>

USFS Post - South (3.8') (exist. B.T.)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____