


T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S 1/4 33 Corner common to sections 33



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1863  
 Original monument POST

**Bearing Trees**  
 Species W. Pine W. Pine  
 Diameter 6 4  
 Bearing N69W N8E  
 Distance 13 lks 23 lks

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1984 By Tony Kerick  
 Location filed Corner Certificate  
 Monument Found 2" iron pipe. John Curo had set a 2" lip. From evidence he found around 1910. Accept this 2" pipe as corner. Set 3" brass cap monument and replaced 2" pipe east side of new monument.

**Bearing Trees, Reference Objects**  
 Species Roak Birch Roak  
 Diameter 9" 9" 8"  
 Bearing N32W N7W N20E  
 Distance 21.19' 37.64' 24.95'

Evidence of Subsequent Corner Restoration

Year of search Dec 2002 By J. Freeman #21367  
Cert. of Survey shows Mon. found

**Bearing Trees, Reference Objects**

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Bearing Trees, Reference Objects**

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Tony Kerick - 1984  
Doc. # 280503