


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4 AND 33, 34 - 143-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Species	Bearing	Trees	Distance
<u>CEDAR</u>	<u>14"</u>	<u>12"</u>	<u>12"</u>
<u>CEDAR</u>	<u>12"</u>	<u>12"</u>	<u>10"</u>
<u>CEDAR</u>	<u>12"</u>	<u>12"</u>	<u>12"</u>
<u>CEDAR</u>	<u>12"</u>	<u>12"</u>	<u>4"</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN GREENE

Location filed COUNTY BOOK B P. 532-533

Monument FOUND CORNER - AND ALL BTS IN GOLD SHARE

Evidence of Subsequent Corner Restoration

Year of search 1916 By HORST

Microfilm - roll 1105 BK 68 P. 24

Find all BIT. 5 and old U.S. stake

Set I. M.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Cedar</u>	<u>6"</u>	<u>N 87-30W</u>	<u>20.3'</u>
<u>Cedar</u>	<u>6"</u>	<u>N 79E</u>	<u>24.0'</u>
<u>Cedar</u>	<u>5"</u>	<u>S 77W</u>	<u>27.7'</u>
<u>Cedar</u>	<u>6"</u>	<u>S 10E</u>	<u>18.6'</u>

Subsequent Corner Restoration

Year surveyed 1986 By Gary Stevenson

Location filed Corner Certificate - Doc # 295273

Monument Find 2" x 48" lip. - replaced with 2" x 48" lip. w/ stamped brass cap. ± 65' N OF E-W fence

Elm 8" S 30° W 48.25'

Tw. Elm 6" N 65° E 21.95'

Elm 12" S 50° E 40.11'

8' steel sign post East 5.0'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - 1987

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____