


Index No. 2-25

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 13 Corner common to sections 12, 13 + 7 + 18 - 142 - 25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>	<u>CEDAR</u>
<u>6"</u>	<u>6"</u>	<u>6"</u>	<u>4"</u>
<u>S20E</u>	<u>S42W</u>	<u>N51E</u>	<u>N60W</u>
<u>6 LKS</u>	<u>17 LKS</u>	<u>21 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1997, June By Lavene Leuelling  
Rejected a found square post for this corner & set a  
galvanized steel pipe at the "lost" position

Cert. Filed: Dec. 8, 1997; Doc. #395053

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Spruce	Spruce	Balsam Fir	Balsam Fir
<u>0.210m</u>	<u>0.190m</u>	<u>0.150m</u>	<u>0.220m</u>
<u>N38W</u>	<u>S65W</u>	<u>S40E</u>	<u>N72E</u>
<u>6.948m</u>	<u>10.710m</u>	<u>3.532m</u>	<u>12.434m</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_