

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
N¹⁴ 17 Corner common to sections B, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument POST

Bearing Trees

Species	<u>BIRCH</u>	<u>BIRCH</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>N68E</u>	<u>S11E</u>	_____
Distance	<u>11K5</u>	<u>212K5</u>	_____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1916 By JAMES FLYNN
 Location filed COUNTY BOOK "C" P. 167
 Monument SET CORNER PROPORTIONALLY
1920 - JAMES FLYNN BOOK "C" P. 387 SET 1 1/2 BY 4"
IRON MONUMENT COUNTY RESURVEY 1920 "E-2"

Evidence of Subsequent Corner Restoration
 Year of search 1982 By CG HWY & SURVEYOR
FIND NOTHING.

Bearing Trees, Reference Objects

Species	<u>N. PINE STUB</u>	<u>W. PINE STUB</u>	_____
Diameter	<u>12"</u>	<u>7"</u>	_____
Bearing	<u>N33E</u>	<u>S14E</u>	_____
Distance	<u>55.0'</u>	<u>59.0'</u>	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

J-7

Subsequent Corner Restoration
 Year surveyed 5/04 By CCSO
 Location filed #2004.001
 Monument Found USFS brass cap, flush,
4'± N. of E. Co. Rd #4, USFS
SW witness a snag, add following:
10" N. Pine N 48° W, 79.15'
10" N. Pine N 2° W, 50.41' *
* distance to double head nail

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
Certificate - Ken Whitehorn - USFS - 1984
Doc. # 274371
Set 2" x 24" galvanized iron pipe filled
with concrete and capped with 3"
stamped brass tablet. Ties: 12" Aspen
551W 117.15'; 8" Birch S8W 72.94'.