


T. 142 R. 26 M. 5TH Coordinates: X _____ Y _____
E 14 14 Corner common to sections 13, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>N. PINE</u>	_____	_____
Diameter	<u>8"</u>	<u>8"</u>	_____	_____
Bearing	<u>N60E</u>	<u>S70W</u>	_____	_____
Distance	<u>10 LKS</u>	<u>12 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1943 By William Okerman
Location filed _____
Monument Found 10" N. Pine West 1.32'
Set 2" x 60" galvanized steel monument
capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration

Year of search 1997, 10-19 By Laverne Leuelling
Re-established corner by single proportionment
between NE corner of Sec. 14 and Meander
corner on N shore of Knights lake.

Cert. Filed: Dec. 8, 1997; Doc. # 395056

Bearing Trees, Reference Objects

Species	<u>R. Pine</u>	<u>Birch</u>	_____	_____
Diameter	<u>12"</u>	<u>8"</u>	_____	_____
Bearing	<u>S50W</u>	<u>N9E</u>	_____	_____
Distance	<u>75.7'</u>	<u>18.0'</u>	_____	_____

Bearing Trees, Reference Objects

<u>Sugar Maple</u>	<u>Sugar Maple</u>	<u>Twin Maple</u>	<u>S. Signpost</u>
<u>0.127m</u>	<u>0.128m</u>	<u>0.128m</u>	_____
<u>S80W</u>	<u>S58E</u>	<u>S53W</u>	<u>W</u>
<u>10.670m</u>	<u>10.798m</u>	<u>10.854m</u>	<u>1.000m</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By LANDECKER (T. Freeman)
Col. S. #485 notes Brass Cap monument
found in pl.