


Index No. Q-20

CASS COUNTY LAND CORNER RECORD

T. 142 R. 26 M. 5th Coordinates: X _____ Y _____
SE 1/16 Corner common to sections 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1998 By NLSEM
Location filed Cass Co. Recorder (J-34)
Monument USFS Brass cap, set at center of SE 1/4.

Evidence of Subsequent Corner Restoration

Year of search 8/2000 By CCSO
Corner and witnesses destroyed by road construction. Set 78" ODIP at NLSEM position, 27 1/2' E. of new E CR #52.

Steel sign post East, 1.7'

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Aspen</u>	<u>BoT G</u>	<u>Steel</u>
Diameter	<u>4"</u>	<u>6"</u>	<u>6"</u>	<u>Sign Post</u>
Bearing	<u>N74°E</u>	<u>S41°W</u>	<u>N46°W</u>	<u>N2°W</u>
Distance	<u>27.45'</u>	<u>70.08'</u>	<u>60.72'</u>	<u>1.5'</u>

Bearing Trees, Reference Objects

Species	<u>Balsam</u>	<u>Maple</u>
Diameter	<u>6"</u>	<u>8"</u>
Bearing	<u>N29°E</u>	<u>S61°E</u>
Distance	<u>122.27'*</u>	<u>83.81'*</u>

*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____