


T. 142 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 34 Corner common to sections 34, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>8"</u>	<u>6"</u>	_____
Bearing	<u>N56E</u>	<u>S77W</u>	_____
Distance	<u>20 LKS</u>	<u>11 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1986 By Walt Curo  
Set corner in C. of N-S Rd in line w/ fence E.  
set 2" X 24" galv. pipe w/ brass cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>w. pine</u>	<u>w. pine</u>	<u>w. pine</u>
<u>28"</u>	<u>14"</u>	<u>6"</u>
<u>N30°W</u>	<u>N50°E</u>	<u>East</u>
<u>80.00'</u>	<u>70.65'</u>	<u>69.58'</u>

X-17

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo 1986  
Doc. # 291473

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_