


Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 142 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>5"</u>	<u>6"</u>	<u>6"</u>	<u>5"</u>
Bearing	<u>S58E</u>	<u>S58W</u>	<u>N45W</u>	<u>N46E</u>
Distance	<u>12 LKS</u>	<u>14 LKS</u>	<u>16 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1980 By Gary Stevenson
Location filed _____
Monument Found decayed wood post and point. Set 2" x 60" concrete filled galvanized iron pipe with marked brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects			
	<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>7"</u>	<u>9"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>N72W</u>	<u>S67W</u>	<u>N61E</u>	<u>S67E</u>
Distance	<u>29.0'</u>	<u>14.64'</u>	<u>35.32'</u>	<u>27.65'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
DOC. # 260979

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____