


T. 142 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-142-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Truss	Distance
<u>Poplar</u>	<u>N 80° W</u>	<u>ELM</u>	<u>SUBS. MAPLE</u>
Diameter <u>18"</u>	<u>6"</u>	<u>6"</u>	<u>16"</u>
Bearing <u>S 24° E</u>	<u>S 80° W</u>	<u>N 4° W</u>	<u>N 80° E</u>
Distance <u>25 LKS</u>	<u>20 LKS</u>	<u>10 LKS</u>	<u>65 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By JOHN Curo
Location filed COUNTY SURVEY RECORD BOOK B' P. 102-104
Monument Find old Govt B.T.S: 18" Poplar S 24° E 25 LKS,
16" Maple N 80° E 65 LKS. SET SQUARE POST
1916 JOHN Curo BOOK B' P. 391-398 FIND POST SET
FROM U.S. GOVT B.T.S SET 2x 48" IRON

Evidence of Subsequent Corner Restoration

Year of search 1918 By G.L.O.
FIND 2" I.P. ALONGSIDE PIPE, SET 2x 36" I.P. W/ BRASS CAP
T 142 N
R 29 W R 28 W
525 530
536 531

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>MAPLE</u>	<u>MAPLE</u>	<u>MAPLE</u>
Diameter <u>12"</u>	<u>16"</u>	<u>10"</u>
Bearing <u>N 72° W</u>	<u>S 80° E</u>	<u>N 16° E</u>
Distance <u>59'</u>	<u>37.50'</u>	<u>49.70'</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>MAPLE</u>	<u>ELM</u>	<u>W. OAK</u>
Diameter <u>8"</u>	<u>8"</u>	<u>22"</u>
Bearing <u>N 77-15 W</u>	<u>S 49-45 W</u>	<u>S 63-15 E</u>
Distance <u>67 LKS</u>	<u>67 LKS</u>	<u>160 LKS</u>

1916 TIES. Book B' 102-104

Subsequent Corner Restoration

Year surveyed 1970 By R.F. Schneider
Location filed RFS - GHS Records
Monument Set 2" I.P. from MC. West and
other corners South and east.
1975 ties: PK on side R.P. S 14° W 117.95'
✓ ✓ ✓ tele box pole E 56.94'
✓ lower blaze 4" Elm N 57° E 9.48'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - BEAR ISLAND VIEW
R.F. SCHNEIDER 1970

8/3/83 Stevenson, Freeman found 2" I.P. on
top of bank E. of road to resort. also 2
1975 RFS ties - tele box pole East is gone
also found maple tie to MC. West of corner
dist checks between MC & Corner

Certificate - Walt Cure - 1985

OCT 2001

CALL FROM OWNER - MAPLE N 69° W WILL
BE TAKEN DOWN. R. KOVANEN VISIT SITE
6" ELM IS GONE
ADDED 7" DBL ASH N 81° E 6.40 TO FACE
MON IS @ TOP OF W/LY SIDE OF DRIVEWAY
CUT.

1916 - Book B' P. 102-104 also on microfilm
roll 105 BK 54B P. 43.

Sept 2003 M. Handwerker * 7452
Cert. of Surv. shows Mon. found

FREEMAN, KRANSE, ALCISSON

1985 - June - checked corner. pulled 2' x 2.5' I.P.
replaced w/ 2" sq x 3" iron w/ stamped aluminum cap.
new B.T.S: 20" Maple S 34° W 91.46'
15" Maple S 67° W 56.61' } all scribed
17" Maple N 69° W 46.28' } "B.T."
6" Elm N 56° E 9.79' }

Corner Certificate - Cure - 1985 - Doc # 292694

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____