


T. 142 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C. # 24 Corner common to sections 17, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. Pine</u>	<u>W. Pine</u>	_____	_____
Diameter	<u>24</u>	<u>10</u>	_____	_____
Bearing	<u>SW</u>	<u>N 30</u>	_____	_____
Distance	<u>340 lbs</u>	<u>27 lbs</u>	_____	_____

same trees as for 1/4 corner.

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed \_\_\_\_\_  
Monument Set 1" x 36" I.P. w/ Br. Cap at  
reared bearing - distance - no evidence  
found of original

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species Raised Mound of stone East of corner.  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Cedar Post  
4" x 4" x 72"  
East  
1.30'

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970