


T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E' 4 21 Corner common to sections 21 & 22



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1873  
 Original monument POST

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Bearing Trees**  
 Species Tam Tam  
 Diameter 5 6  
 Bearing N70E S30W  
 Distance 27 lks 19 lks

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1918 By GLO  
 Location filed \_\_\_\_\_  
 Monument 1" x 3/16" I.P. w/ Br. Cap set at proportional point - no evidence at original.

**Evidence of Subsequent Corner Restoration**  
 Year of search 1965 By DNR-Engineering  
Map and notes in file  
Found brass cap monument

**Bearing Trees, Reference Objects**  
 Species Poplar Poplar  
 Diameter 6 7  
 Bearing N35 1/2 E N68 3/4 W  
 Distance 44 lks 15 lks

**Bearing Trees, Reference Objects**  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1965  
Found GLO monument in good condition.  
8" Ash S62E 25.3'; 7" Ash S19W 24.4'.