


Index No. R3

CASS COUNTY LAND CORNER RECORD

T. 14R R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N14 30 Corner common to sections 19, 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

|          |               |               |       |
|----------|---------------|---------------|-------|
| Species  | <u>Poplar</u> | <u>Poplar</u> | _____ |
| Diameter | <u>3</u>      | <u>3</u>      | _____ |
| Bearing  | <u>S32 E</u>  | <u>S86W</u>   | _____ |
| Distance | <u>39 lks</u> | <u>40 lks</u> | _____ |

Original Bearing Trees Found

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1917 By GLO  
Location filed \_\_\_\_\_  
Monument Set 1" x 3/8" I.P. w/Br. Cap at record distance. No evidence found of original.

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman  
Found GLO monument in good condition

Bearing Trees, Reference Objects

|          |                  |                 |       |
|----------|------------------|-----------------|-------|
| Species  | <u>H. Maple</u>  | <u>H. Maple</u> | _____ |
| Diameter | <u>10</u>        | <u>8</u>        | _____ |
| Bearing  | <u>S89 1/2 W</u> | <u>N87-15W</u>  | _____ |
| Distance | <u>212 lks</u>   | <u>210 lks</u>  | _____ |

Bearing Trees, Reference Objects

|               |               |               |                   |
|---------------|---------------|---------------|-------------------|
| <u>R. Oak</u> | <u>R. Oak</u> | <u>R. Oak</u> | <u>Cedar post</u> |
| <u>9"</u>     | <u>8"</u>     | <u>9"</u>     | <u>4"x4"x72"</u>  |
| <u>S59 E</u>  | <u>S7 E</u>   | <u>S31 W</u>  | <u>South</u>      |
| <u>55.30'</u> | <u>49.50'</u> | <u>76.80'</u> | <u>1.80'</u>      |

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - HARBOR SPRINGS  
HAROLD CURB 1961

CERTIFICATE - BILL OKERMAN - 1970

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_