


Index No. T-11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C 44 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1918  
Original monument 1" X 3/8" L.P. w/ Br. Cap

Original Evidence Found  
Year of search 1990 By USFS  
Monument found GLO Brass Cup

Bearing Trees  
Species W. Pine Poplar \_\_\_\_\_  
Diameter 18 8 \_\_\_\_\_  
Bearing N70E N50 1/2 W \_\_\_\_\_  
Distance 62 lks 225 lks \_\_\_\_\_

Original Bearing Trees Found  
Species W. Oak R. Oak W. Oak Sign Post  
Diameter 12" 6" 7" \_\_\_\_\_  
Bearing N40E S30E S24W North &  
Distance 109.00 87.55 92.25 South  
60d spk 60d spk 60d spk

Subsequent Corner Restoration  
Year surveyed 3/2001 By CCSO  
Location filed CCSO  
Monument GLO Brass Cap, flush, on E. Co. Rd. #153. 1990 witness trees in good condition

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

T-11

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_