


T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
SMC 1/4 Corner common to sections 11



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1933
Original monument 1" x 3/16" Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species R. Oak
Diameter 6
Bearing N55 1/2 E
Distance 51 lks

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species R. Pine R. Oak
Diameter 4" 16"
Bearing N74 E S20 E
Distance 16.20' 26.80'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1971 Certificate - William Okerman