


T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	B. Oak	W. Pine	hnd	elm
Diameter	<u>9"</u>	<u>40"</u>	<u>10"</u>	<u>10"</u>
Bearing	<u>S30W</u>	<u>S55E</u>	<u>N60W</u>	<u>N20E</u>
Distance	<u>48 lks</u>	<u>18 lks</u>	<u>27 lks</u>	<u>124 lks</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURD  
 Location filed COUNTY RESURVEY PLAT "E-57"  
 Monument 2 1/4 x 4 1/8" I.M.  
1921, E.B. HORST - COUNTY RESURVEY PLAT "E-57" 2x4 1/8"  
1915, E.B. HORST BOOK C' P44 SET I.M. I.M.  
1919, E.B. HORST, BOOK C' P471 FND I.M.

Evidence of Subsequent Corner Restoration

Year of search 1915 By HORST  
microfilm - roll 115 BK 78 P 90  
Set I.M.s at W 1/16, 1/4, E 1/16

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate David Landecker  
Doc. # 327267  
Found 1/4" capped iron pipe. Ties:  
BT tag on 8' sign post N45W 3.83'  
BT tag on 8' sign post N45E 3.33'  
27" W. Pine 57W 100.17'