


Index No. 41

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W14 18 Corner common to sections 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	_____
Diameter	<u>8"</u>	<u>7"</u>	_____
Bearing	<u>S 35W</u>	<u>S 30 E</u>	_____
Distance	<u>12 lks</u>	<u>92 lks</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. HORST  
Location filed COUNTY RESURVEY PLAT "E-59"  
Monument 2x48" I.M.  
1921, E.B. HORST, BOOK "C" P473 SET 2x48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1991 By David Landecker  
Set 3/4" aluminum rod with stamped aluminum cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Red Oak</u>	<u>Red Oak</u>
<u>7"</u>	<u>14"</u>	<u>11"</u>
<u>N 5 E</u>	<u>N 60 E</u>	<u>S 79 E</u>
<u>65.10'</u>	<u>67.14'</u>	<u>100.43'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - David Landecker  
Doc. # 327269

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_