


T. 142 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 17 Corner common to sections 16, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1813  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Poplar</u>	<u>Buck</u>	_____	_____
Diameter	<u>6</u>	<u>4</u>	_____	_____
Bearing	<u>N37W</u>	<u>N75E</u>	_____	_____
Distance	<u>3 lks</u>	<u>6 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By John Curo  
Location filed County RESURVEY PLAT "E-59"  
Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1990 By David Landecker  
Found 2" capped iron monument.  
Stamped cap.

1916-E. B. Horst - microfilm - roll 105 BK 546 P. 20  
Start E. from corner

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Ash</u>	<u>Burr Oak</u>
<u>4"</u>	<u>5"</u>	<u>4"</u>
<u>WEST</u>	<u>N40E</u>	<u>S30E</u>
<u>13.21'</u>	<u>4.89'</u>	<u>27.43'</u>

Subsequent Corner Restoration

Year surveyed 1999 By Landecker & Assoc  
Location filed CCSO  
Monument Certificate of Survey indicates  
brass cap monument in place.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - David Landecker  
Doc. # 326711