


T. 142 R. 31 M. 57H Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees			
Species	Y. Pine	Y. Pine	Y. Pine
Diameter	<u>18"</u>	<u>14"</u>	<u>18"</u>
Bearing	<u>N83E</u>	<u>N59W</u>	<u>S65W</u>
Distance	<u>37 lks</u>	<u>25 lks</u>	<u>31 lks</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1910 By JOHN CURR

Location filed COUNTY SURVEY RECORD BOOK "A" P. 290-291

Monument TWO IRON MONUMENT SET BY MIDDLETON IN 1906 FROM STUMPS OF ORIG. BITS.

also on microfilm - Roll 105 BK 50 P. 6-7

Bearing Trees, Reference Objects			
Species	OLD 18" STUMP	OLD STUMP	OLD STUMP
Diameter	18"	<u>14"</u>	<u>18"</u>
Bearing	<u>N83-14E</u>	<u>N61W</u>	<u>S64W</u>
Distance	<u>24.60'</u>	<u>16.42'</u>	<u>20.45'</u>

Evidence of Subsequent Corner Restoration p. 10

Year of search 1918 By GLO

Fd. 1" gas pipe + stumps of original BITS

Set Br. Cap 2" x 36" north and alongside

Bearing Trees, Reference Objects			
Oak	Pine	Pine	Pine
<u>3</u>	<u>4</u>	<u>4</u>	<u>4</u>
<u>N79-45E</u>	<u>S12-30E</u>	<u>S67-15W</u>	<u>N33W</u>
<u>38 lks</u>	<u>19 lks</u>	<u>40 lks</u>	<u>61 lks.</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1970

Found GLO monument in good condition

11" N. PINE N37E 28.9'