


T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E14 19 Corner common to sections 19, 20



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>1. Pine</u>	<u>Poplar</u>	_____	_____
Diameter	<u>12</u>	<u>5</u>	_____	_____
Bearing	<u>N50E</u>	<u>N38W</u>	_____	_____
Distance	<u>15 lks</u>	<u>10 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN Curo  
 Location filed COUNTY BOOK B. P446-454  
 Monument TWO IRON PIPE SET BY CANTFIELD MOUND BUILT  
B.T STUMP: 12" J. PINE N50E 15 LKS SET 2 1/2 x 4 1/2"  
GALV. I.P. W/ CAP  
1915, JOHN Curo, COUNTY RESURVEY PLAT, E-600" 2 1/4 x 4 1/2" T.M.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1914 By Curo  
microf. l.m - roll 115 BK 92 P. 3  
Find stumps of both B.T.S - and 1 1/4 x 12"  
iron set by Cantfield

Bearing Trees, Reference Objects

<u>Pine stump</u>	<u>Pine stump</u>	_____	_____
<u>S22-35E</u>	<u>S59-45W</u>	_____	_____
<u>35.5 LKS</u>	<u>57.2 LKS</u>	_____	_____

Subsequent Corner Restoration P-5

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - U.S. GOVT SURVEY SEC 20-142-31  
WILLIAM OKERMAN 1974

1991 Certificate - David Landecker  
Doc # 536715  
Found 2" iron pipe monument. Set  
2"x48" iron pipe with stamped brass  
cap. TIES: 7" W. Pine N80W 37.81'; 6"  
Burr Oak S60W 51.40'; 7" W. Pine  
S36E 33.47'

May 1916, Twp rd order shows no survey