


T. N 2 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 25 Corner common to sections 25 AND 30-14 2-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	<u>R. Oak</u>	<u>B. Birch</u>	_____	_____
Diameter	<u>4"</u>	<u>3"</u>	_____	_____
Bearing	<u>S 45 E</u>	<u>N 46 W</u>	_____	_____
Distance	<u>8 lks</u>	<u>17 lks.</u>	_____	_____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO

Location filed _____

Monument Set 1" x 36" L.P. w/ Br. Cap at record distance - no evidence found of original.

Evidence of Subsequent Corner Restoration

Year of search 1974 By BLM

Fed. Br. Cap and 2 BT's as per 1917 survey.

Bearing Trees, Reference Objects

Species	<u>Oak</u>	<u>Poplar</u>	_____	_____
Diameter	<u>4</u>	<u>5</u>	_____	_____
Bearing	<u>S 69 E</u>	<u>N 74 3/4 W</u>	_____	_____
Distance	<u>59 lks</u>	<u>76 lks</u>	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search June 2005 By T. Freeman #21367

Cert. of Survey shows GLO monument found