


T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Ash SUGAR
Diameter 10" 8"
Bearing SSE N50E
Distance 18LKS 14LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1914 By F.A. DENNER
Location filed COUNTY BOOK 2 P. 551
Monument From both GWT B.T.S. SET 4x4x4E 1/4" GALVANIZED POST

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM
SET 24" COPPER COATED STAKE 8" BELOW SURFACE
T143N R25W
4 528
4 533
1976

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

ALUM POST W/CAP ALUM POST W/CAP
2 1/2 x 28" 2 1/2 x 28"
N60E S50E
45.5' 50.2'

V-11 Subsequent Corner Restoration

Year surveyed 4/2001 By CCSO
Location filed file # 2001.011
Monument Found 60d spike, down 0.5',
3'± E. of ♀ CR #137 on fence line
East. Also Alum. Ref. mon. and
Maple N50°W. Add the following:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - Walter Curo
Dxx. # 326346
Found 1/2" copperweld rod with orange
cap 8" below road surface.
7" Maple N50W 87.81'
8" Maple N30W 83.71'
2 1/2" alum. ref. mon. S50E 50.2'

P. Pole S18°W, 142.00' to dbl. hd. nail