


T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
MC # 24 Corner common to sections 28,33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>White</u>	<u>BALEAM</u>	
<u>5"</u>	<u>6"</u>	
<u>N20W</u>	<u>SOUTH</u>	
<u>8 LKS</u>	<u>4 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

o = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1985 By Gary STEVENSON
Corner Certificate - Doc # 285525
Set 2x2x36" monument w/ aluminum cap
- Set from R.E. Schneider information w/
support of BLM.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Cedar</u>	<u>7"</u>	<u>N17E</u>	<u>5.36'</u>
<u>Cedar</u>	<u>13"</u>	<u>S80W</u>	<u>14.78'</u>
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - 1985

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____