


T. 143 R. 26 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 Corner common to sections AND 6-143-25



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>
Diameter	<u>10"</u>	<u>14"</u>
Bearing	<u>S 28 E</u>	<u>N 52 W</u>
Distance	<u>18 LKS</u>	<u>4 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1976 By BLM

Location filed SEC. OF STATE

Monument SET 24" COPPER WELD 6" BELOW SURFACE W/ COPPER CAP  
T143N  
R 26 W R 25 W

Bearing Trees, Reference Objects <sup>1/4</sup>

Species	<u>ALUM POST W/ CAP</u>	<u>ALUM POST W/ CAP</u>	<u>BLM 1976</u>
Diameter	<u>2 1/2 x 28"</u>	<u>2 1/2 x 28"</u>	
Bearing	<u>N 44 E</u>	<u>N 24 W</u>	
Distance	<u>61.8'</u>	<u>55.8'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1990 By WM OSUFSEN

Find 24" ROD w/ COPPER CAP BY BLM - 1976

Bearing Trees, Reference Objects

<u>BALSAM</u>	<u>AL. POST</u>	<u>AL. POST</u>
<u>7"</u>		
<u>N 67 E</u>	<u>N 24 W</u>	<u>N 44 E</u>
<u>48.27</u>	<u>55.83</u>	<u>61.78</u>

C-25

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO

Location filed CCSO

Monument Found copper weld monument down 0.5', 3' E. of E CR #158. Also 1976 witnesses. Add the following

6" Spruce N 76° W, 90.34\*

P. Pole S 77° W, 35.42\*

\*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

CERT. BY WM OSUFSEN 1990

Doc # 319605