


T. 143 R. 26 M. 574 Coordinates: X _____ Y _____
N 1/4 15 Corner common to sections 10, 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Species	Bearing	Trees
<u>SPRUCE</u>	<u>551W</u>	<u>4LKS</u>
<u>SPRUCE</u>	<u>N 83E</u>	<u>5LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By E. B. Horst

Location filed COUNTY BOOK "C" 1917

Monument END GOVT BITS: 8" SPRUCE STUMP N 83E 5LKS
4" SPRUCE STUB 551W 4LKS

Evidence of Subsequent Corner Restoration

Year of search 1959 By DNR - Engineering

Map notes in file

Found CCC Monument east of road
6" spike for corner

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>CEDR STUMP</u>	<u>8"</u>	<u>S 73E</u>	<u>42'</u>
<u>CEDR STUMP</u>	<u>8"</u>	<u>N 81W</u>	<u>48.9'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>8" Aspen</u>	<u>N 5 B.C.</u>	<u>NE</u>	<u>58.47'</u>
<u>CCC marker</u>	<u>6" Aspen</u>	<u>East</u>	<u>22.6'</u>
<u>6" Aspen</u>	<u>N 5 B.C.</u>	<u>SE</u>	<u>31.51'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

J-15

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - John Walker - DNR - 1988
Doc # 303528
Set 1 1/4 x 1 1/4 x 20" mon. w/ alum. cap.
" on Boulder 2 1/2 x 2 1/2" WEST 23.76'
15" CMC punch hole w. end 57W 67.33'
" " " " E. end 512E 68.60'