


Index No. N.0-10.0

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

W 1/16 Corner common to sections 13,22



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 5/1975, Rychner, E.K. DNR

Year of search \_\_\_\_\_ by \_\_\_\_\_

Original monument Set Spike

Monument found \_\_\_\_\_

Certificate of Survey, G-321, Mud-Goose Management Area

Bearing Trees

Original Bearing Trees Found

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 3/2013 By A.D. Larson, LS 14455

Year of search 7/2015 By CCHD/SO

Location filed: Certificate of Survey, #6112

Location filed: #2015.007

Monument: Found Railroad spike

Monument: Found RR spike down 0.2', 1' N. of centerline CSAH #65. Remove prior to construction.

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Species R. Oak P. Pole Steel Sign \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter 14" Post \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing N 44° E S 68° E N 5° E \_\_\_\_\_

Distance \_\_\_\_\_

Distance 80.02' 128.00' 45.2' \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 11/2015 By CCHD/SO

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: #2015.007

Location filed: \_\_\_\_\_

Monument: Reset RR spike 1.5' N. of new centerline CSAH #65.

Monument: \_\_\_\_\_