


T. 143 R. 27 M. 5TH Coordinates: X NE 24 Corner common to sections 13, 24 AND 18, 19-143-26 Y \_\_\_\_\_



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1872

Original monument Post

Bearing Trees			
Species	<u>Spruce</u>	<u>Spruce</u>	<u>Spruce</u>
Diameter	<u>7"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>N30W</u>	<u>S72W</u>	<u>S28E</u>
Distance	<u>10LKS</u>	<u>13LKS</u>	<u>7LKS</u>

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed 7 By Geo. Ralph

Location filed COUNTY SURVEY RECORD BOOK B' P. 97

Monument FIND OLD POST - OLD BITS! 12" TAM S94.30W 8.4', 8" TAM N16-30W 7.4', 6" SPRUCE S-E 7.3'

also on microfilm - roll 115 BK82 P. 42

Bearing Trees, Reference Objects		
Species	<u>TAM.</u>	<u>CEDAR</u>
Diameter	<u>8"</u>	<u>12"</u>
Bearing	<u>N26-30E</u>	<u>S80W</u>
Distance	<u>47'</u>	<u>59.2'</u>

**Evidence of Subsequent Corner Restoration**

Year of search 1925 By Co. Hwy Dept

State RD # 4

corner

Bearing Trees, Reference Objects	
<u>Tam stump</u>	<u>Tele. Pole</u>
<u>12"</u>	_____
<u>SE</u>	<u>S</u>
<u>43.7'</u>	<u>29.0'</u>

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

1986 Certificate - Ken Whitehorn

Doc. # 289685

Set 2 1/2" x 24" iron pipe with 3" brass tablet down 6".

Power Pole N77W 222.54'

1 1/2" Ash S4W 92.31'

12" Ash S28E 129.86'

8 1/2" Ash N7E 92.74'

1998 - NLSEM RLS #16089 replaced bent 1986 monument with Alum rod monument, and filed new certificate.

MAY 2004 - R. KOVANEN FOUND ALUM ROD TOP 10" BENT - CUT OFF 3/4" ALUM ROD @ 8" BELOW GRAVEL SURFACE