


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
E1422 Corner common to sections 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species Tam Tam
 Diameter 5" 4"
 Bearing N32W N69E
 Distance 12LKS 5LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1999 By L. LEUELLING (NLSM)
set an alum. capped aluminum rod midway
and on line between the SE + NE corners
of Sec. 22.
 CERT. OF LOCATION 5-30-99
 DOC. NO. 413421

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
Tamarack Steel signpost Tamarack Tamarack
6" 5" 6"
S 76° E S 5° W S 37° W N 87° W
19.40' 1.68' 8.96' 21.32'
(5.973m) (0.512m) (2.732m) (6.497m)

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____