


Index No. P21

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
E1423 Corner common to sections 23,24



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Bearing Trees	
Species <u>ELM</u>	<u>FYR</u>
Diameter <u>12"</u>	<u>10"</u>
Bearing <u>N25E</u>	<u>N12W</u>
Distance <u>22LKS</u>	<u>32LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By NLSM RLS # 16089
Set a 2" x 4' galv. steel pipe w/ brass cap up 8"

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Maple	Maple	Maple	Std. sign post (FS 54-9)
<u>5"</u>	<u>6"</u>	<u>6"</u>	<u>N 71° W</u>
<u>N 5° W</u>	<u>S 39° E</u>	<u>S 38° W</u>	<u>1.37'</u>
<u>21.54'</u>	<u>49.07'</u>	<u>25.54'</u>	<u>to N Flange</u>

~~Subsequent Corner Restoration~~

Year surveyed _____ By _____
Location filed _____
Monument _____

CERT. OF LOCATION 5/17/99
DOC. # 412851

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____