


T. 143 R. 27 M. 5th Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25,36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search 1915 by J. Curo
Monument found Gov't BT
County Book B, pages 455-462

Bearing Trees

Species	<u>Elm</u>	<u>Birch</u>
Diameter	<u>10"</u>	<u>6"</u>
Bearing	<u>N 6° W</u>	<u>S 66° W</u>
Distance	<u>14 lks</u>	<u>13 lks</u>

Original Bearing Trees Found

Species	<u>Birch</u>
Diameter	<u>6"</u>
Bearing	<u>S 66° W</u>
Distance	<u>13 lks</u>

Subsequent Corner Restoration

Year surveyed 2/1915 By F.A. Donner
Location filed: Survey Record #328, Book B, page 455 and Curo
Monument: Set 60d spike
Curo Book 79, page 11

Evidence of Subsequent Corner Restoration

Year of search 7/1920 By J.H. Flynn, County Surveyor
Location filed: Curo Book 152, page 17
Monument:
Indicates corner and the following:

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Birch</u>	<u>W. Pine stump</u>
Diameter	<u>8"</u>	<u>16"</u>	<u>10"</u>
Bearing	<u>N 69°35' W</u>	<u>S 50°15' E</u>	<u>N 51° E</u>
Distance	<u>15.80'</u>	<u>55.05'</u>	<u>52.35'</u>

Bearing Trees, Reference Objects

Species	<u>W. Birch</u>	<u>W. Birch</u>
Diameter	<u>13"</u>	<u>8"</u>
Bearing	<u>S 68° E</u>	<u>N 40° W</u>
Distance	<u>49.5'</u>	<u>22.5'</u>

Subsequent Corner Restoration

Year surveyed 10/1969 By C. Krause
Location filed: USFS T143R27 Book 1, page 5
Monument: None
Corner falls in Blacktop road found no evidence of trees.

Evidence of Subsequent Corner Restoration Found

Year of search 8/2019 By T.L. Freeman, LS 21367
Location filed: Certificate of Location, A000652198
Monument: Found USFS monument
down 0.05', on center line CSAH #4.

8/1997, R. Main
USFS T143R27 Book 1, page 5
GPS position in center of County Road #4 in line with old
fence line north.

12/1998, L. Leuelling
Certificate of Location
Set USFS 2"x 24" iron pipe with brass cap, below road surface
and witnessed as follows:
6" Oak (twin), N 2° E, 80.88'
5" Aspen, S 47° E, 100.80'
5" Aspen, S 6° E, 68.85'
Steel Post, S 41° E, 43.90'

11/2006, CCHD/SO
#98020
Reset USFS monument, down 0.05', on center line CSAH #4,
add the following:
P. Pole, S 66° E, 99.70'
8" Aspen, S 02° E, 74.81'

