


T. 143 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 36 Corner common to sections 25,36 and 30,31-143-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Fir	Birch	Fir	Birch
Diameter	<u>10"</u>	<u>8"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>S 38° E</u>	<u>S 78° W</u>	<u>N 40° E</u>	<u>N 59° W</u>
Distance	<u>21 lks</u>	<u>9 lks</u>	<u>33 lks</u>	<u>13 lks</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By F.A. Donner  
Location filed: Survey Record #328, Book B, page 455 and Curo Monument:  
Curo Book 79, page 12, states We are unable to find any of the old B.T.s

Evidence of Subsequent Corner Restoration

Year of search 7/1920 By J.H. Flynn, County Surveyor  
Location filed: Curo Book 152, page 17  
Monument:  
54+99 N.W. Cor. Sec. 31

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1986 By G. Robertson  
Location filed: USFS T143R26 Book 2, page 17  
Monument: Set 2.5"x 24" iron pipe with brass cap  
Slightly below road surface and witness as follows:  
12.2" W. Oak N 63° E, 107.44'  
5.5" W. Oak S 03° W, 64.76'  
5.8" R. Oak N 08° W, 47.78'  
  
11/2006, CCHD/SO  
#98020  
Set 1"x 18" Aluminum county monument, down 0.05', 1' +,-  
North of center line CSAH #4.  
  
8/2019, T.L. Freeman, LS 21367  
Certificate of Location, A000652199  
Filed on the above information.


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. V 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 27 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 36 Corner common to sections 25, 36 AND 30, 31-143-26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	Fir	Birch	Fir	Birch
Diameter	10"	8"	8"	10"
Bearing	S38E	S78W	N40E	N59W
Distance	21 LKS	9 LKS	33 LKS	13 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1986 By Ken Whitehorn  
Location filed \_\_\_\_\_  
Monument Set 2 1/2" x 24" galvanized iron pipe with magnet at base and 3" stamped brass tablet.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	B. Oak	W. Oak	W. Oak
Diameter	5 1/2"	5 1/2"	12"
Bearing	N8W	S3W	N63E
Distance	47.78'	64.76'	107.44'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1986 Certificate - Ken Whitehorn  
Doc. # 289689

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_