


T. 143 R. 27 M. 5TH Coordinates: X _____ Y _____
MC# 17 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| | | | |
|----------|---------------|---------------|-------|
| Species | <u>Tam</u> | <u>Tam</u> | _____ |
| Diameter | <u>6"</u> | <u>5"</u> | _____ |
| Bearing | <u>N13W</u> | <u>N2E</u> | _____ |
| Distance | <u>465LKS</u> | <u>500LKS</u> | _____ |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1999 By L. LEWELLING (NLSM)
Set a 3/4" x 16' alum. rod w/ 3/4" Alum. cap set 10" above grd. Set as WC to MC 50m North and on line. MC hits in Bay River. CERT. OF LOCATION 5-30-99 DCC. NO - 413417

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | |
|---------------------|---------------------|---------------------|
| <u>St. Signpost</u> | <u>St. Signpost</u> | <u>St. Signpost</u> |
| <u>N 7° E</u> | <u>N 86° E</u> | <u>N 88° W</u> |
| <u>2.20'</u> | <u>2.07'</u> | <u>2.07'</u> |
| <u>(0.671m)</u> | <u>(0.631m)</u> | <u>(0.631m)</u> |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____