


Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2, 3 AND 34, 35 - 144-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	<u>Tam</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>10"</u>
Bearing	<u>S30W</u>	<u>N78W</u>	<u>N40E</u>
Distance	<u>3 LKS</u>	<u>5 LKS</u>	<u>8 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By HARRY S. TODD
Location filed COUNTY SURVEY RECORD BOOK A P. 532-535
Monument FIND OLD CORNER B.T.S: 6" TAM N78W 5 LKS.
10" TAM N40E 8 LKS SET 2" x 48" GALV. I.P.
WITH 3" CAP.

1915 E.B. HORST BOOK Y P. 272 FIND 2" x 48" I.M.
- also on microfilm - roll 115 BK 71 P. 4

Bearing Trees, Reference Objects

Species	<u>BK 71 P. 65</u>	<u>take cap off iron - replace</u>
Diameter	<u>with brass cap</u>	_____
Bearing	_____	_____
Distance	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept.
State Road #4
iron monument

1912 - also on microfilm - roll 115 BK 74 P. 56-57
P. 62 - set 4" x 48" pipe for corner

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Aspen</u>
Diameter	<u>4"</u>	<u>3"</u>
Bearing	<u>S</u>	<u>SW</u>
Distance	<u>38.9'</u>	<u>50.1'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____