

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 5TH Coordinates: X NE 13 Corner common to sections 12, 13 AND 7, 18 - 143-27 Y



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>Poplar</u>	<u>Poplar</u>	<u>Poplar</u>	<u>Birch</u>
<u>5"</u>	<u>7"</u>	<u>7"</u>	<u>8"</u>
<u>West</u>	<u>North</u>	<u>N40E</u>	<u>55SE</u>
<u>5LKS</u>	<u>8LKS</u>	<u>25LKS</u>	<u>22LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? By GEO RALPH
Location filed COUNTY SURVEY RECORD BOOK B P. 94-95
Monument IRON STAKE

Evidence of Subsequent Corner Restoration

Year of search 1925 By Co Hwy Dept
State Rd #4
Corner

also on microfilm - roll 115 BK82 P. 32

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>MAPLE</u>	<u>10"</u>	<u>N55-30E</u>	<u>66.4'</u>
<u>BIRCH</u>	<u>12"</u>	<u>S37-30W</u>	<u>72.0'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Tele. Pole</u>	<u>_____</u>	<u>_____</u>	<u>_____</u>
<u>Maple stump</u>	<u>_____</u>	<u>_____</u>	<u>_____</u>
<u>NW</u>	<u>33.6'</u>	<u>NE</u>	<u>75.7'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1986 Certificate - Walter Curo
Doc # 291479
Found brass cap monument in concrete
8" below surface of County Road # 154.
6" Elm N66W 76.48';
8" Elm N20E 91.88';
Power Pole S43W 50.98';
24" Spruce S43E 168.10'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____