


T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
E 1/4 26 Corner common to sections 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Cedar</u>	<u>Cedar</u>	
Diameter <u>10"</u>	<u>14"</u>	
Bearing <u>N36W</u>	<u>N80E</u>	
Distance <u>24LKS</u>	<u>25LKS</u>	

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

O = Corner

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK B P 220-242
Monument FIND OLD GOV'T BIT: DOWN 10" CEDAR N36W 24 LKS, ROOTS 14" CEDAR N80E 25 LKS

Evidence of Subsequent Corner Restoration

Year of search 1928 By GLD
Found both cedar Stumps and 2 1/2" galv. l.p. up 2' with unmarked iron cap.

also on microfilm - roll 115 BK 77 P. 37, 42, P. 50

Bearing Trees, Reference Objects Set I.M.

Species		
Diameter		
Bearing		
Distance		

1964 Co. Hwy Dept - Co RD # 8
Found l.p. in place 297' W. of C

Bearing Trees, Reference Objects

1959 - Co Hwy Dept - Co RD # 8
l.p. in place 297' W. of C

Subsequent Corner Restoration

Year surveyed 1975 By Co Hwy Dept
Location filed Co RD # 4
Monument 2" l.p. in place

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1981
Doc. # 264936
Found 2 1/2" capped galvanized iron pipe as set in 1916.
7" Cedar N34W 60.30';
5" Ash S31E 55.00';
7" Ash S86E 105.75'