


T. 143 R. 28 M. 5TH Coordinates: X _____ Y _____
MC # 18 Corner common to sections 36 AND 31-143-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species NO RTS.
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1920 By GLO
Location filed _____
Monument set stake 6.78 chains N. of MC on S. side of river

Evidence of Subsequent Corner Restoration

Year of search 1986 By Walt Curo
Corner Certificate - Doc # 291629
set 5/8" x 10' aluminum monument 8' in ground for WC MC. corner is 465.52' (GLO was 447.48') N. of MC. and 1469.70' S. of 1/4 corner 45' N. of river.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1986