


T. 143 R. 29 M. 5TH Coordinates: X _____ Y _____
NES Corner common to sections 4, 5 AND 32, 33-144-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>5"</u>	<u>12"</u>	<u>7"</u>	<u>8"</u>
Bearing	<u>N85E</u>	<u>N79W</u>	<u>S87W</u>	<u>S87E</u>
Distance	<u>72 LKS</u>	<u>55 LKS</u>	<u>83 LKS</u>	<u>49 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK # P254-255
Monument FIND OLD GOVT B.T.S: 15" CEDAR N85E 48.2', 12" CEDAR N79W 36.3', 7" CEDAR S87W 54.0', 8" CEDAR S87E 54.8', 8" CEDAR S87E 32.3' FIND OLD SPAKE SET STAKE

Evidence of Subsequent Corner Restoration

Year of search 1923 By HORACE DUNAWAY
FND 12" CEDAR BIT DOWN SET 4" IRON IN 3' SQUARE CONCRETE BLOCK

DUNAWAY
32 133
519

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>CEDAR</u>	<u>SPRUCE</u>	_____	_____
<u>8"</u>	<u>14"</u>	_____	_____
<u>N55-20E</u>	<u>N31-45W</u>	_____	_____
<u>188'</u>	<u>295.4'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed 1924 By GLO
Location filed SEC. OF STATE
Monument Found 3" Dia TP Filled w/ Concrete in 18" SQUARE CONCRETE BASE ALSO Found orig BT: 14" CEDAR N79W 55 LKS (DOWN)
NEW B.T.S: 8" Poplar N81E 167 LKS
10" Poplar N33-45W 185 LKS

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____