


T. 143 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 18 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>ROAK</u>	<u>R. OAK</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>S 60 E</u>	<u>S 71 W</u>	_____
Distance	<u>20 LKS</u>	<u>18 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1919 By GLO
Location filed Sec. of State
Monument Find both gaut BITS SE one dead.
Set 1x36" 1 1/2" w/ brass cap 11/57
14/518
1919

Evidence of Subsequent Corner Restoration

Year of search 1983 By Walter Curo
Found 1" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	<u>R. OAK</u>	<u>R. OAK</u>	_____
Diameter	<u>16"</u>	<u>12"</u>	_____
Bearing	<u>N 52-15 W</u>	<u>S 27 E</u>	_____
Distance	<u>43 LKS</u>	<u>69 LKS</u>	_____

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>Maple</u>	<u>Maple</u>
<u>12"</u>	<u>13"</u>	<u>6"</u>
<u>N 8 W</u>	<u>N 72 E</u>	<u>S 40 E</u>
<u>62.83'</u>	<u>36.40'</u>	<u>62.83'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1983
Doc. # 268844
1999 - Landecker - Col S # 487 notes
monument found impl.
Mar 2003 T. Freeman # 21367
Cert. of Surv. shows Mon. found