


T. 143 R. 31 M. 5TH Coordinates: X _____ Y _____
E¹¹⁶ Corner common to sections 5, 32-144-31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1931
 Original monument 2x36" iron/brass cap 1931 E¹¹⁶ 532/55

Bearing Trees

Species Tam. p/c 2" 1.8.4' above ground
 Diameter 8" long 8" dia Set by Cass Co. Surveyor
 Bearing 2" inground N15-30W
 Distance along side iron 97.45

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1925 By Min. Hwy Dept
 Location filed R/W map in Recorder's office - Walker
 Monument iron monument & brass cap 174.5' E. of C
also 2" iron pipe Northwesterly

Evidence of Subsequent Corner Restoration

Year of search 1915 By N. D. Gorman
microfilm - roll 115 BK 87 P. 20.
Set 3x3x24" Tam. stake

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Dead Tam Dead Tam
7" 6"
S51-49W N31-15E
37.00' 46.50'

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____