

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Year surveyed \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

By \_\_\_\_\_

Subsequent Corner Restoration

Species Tam 4"  
 Diameter 5" 5" 5"  
 Bearing N88E S32E S39W N74W  
 Distance 834Ks 17Ks 84Ks 44Ks

Bearing Trees

Year surveyed 1876  
 Original monument lost

Original Government Survey

EXISTING SURVEYS

T. 144 R. 25 M. 577 Coordinates: X 10,11,14,15  
 Corner common to sections \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

Index No. 517

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Jim Parker - 1985  
Set obliterated from 1900 Corp info - set  
5/8" X 10' aluminum rod w/ cap,  
2" Tamarack N 58° E 7.26'  
4" Tamarack S 40° E 18.67'  
4" Tamarack S 60° W 1.29'  
2" Tamarack N 75° W 18.12'  
Doc. # 281711

Bearing Trees, Reference Objects


Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Evidence of Subsequent Corner Restoration

Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Original Bearing Trees Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_  
 Original Evidence Found

○ = Corner



Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_