


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____
N 1/4 34 Corner common to sections 27, 34



EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1876</u>	Year of search _____ by _____
Original monument <u>Post</u>	Monument found _____

Bearing Trees

Species	<u>No Trees</u>
Diameter	_____
Bearing	_____
Distance	_____

Original Bearing Trees Found

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 12/1983 By J.R. Worcester, CCHD
 Location filed: S.P. 11-603-07
 Monument:
 Indicates corner assumed on centerline at Station 365+41.7

Evidence of Subsequent Corner Restoration

Year of search 9/1984 By J.H. Parker, LS 9235
 Location filed: Certificate of Location
 Monument: Set 5/8"x 36" aluminum rod monument with cap, at lost position, down 0.3'.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	<u>Balsam</u>	<u>Cedar</u>
Diameter	<u>12"</u>	<u>10"</u>
Bearing	<u>N 1° E</u>	<u>S 8° E</u>
Distance	<u>63.73'</u>	<u>74.90'</u>

Subsequent Corner Restoration

Year surveyed 5/1989 By W.E. Curo, LS 11395
 Location filed: Curo File 1983
 Monument:
 Subdivision in file indicates this corner was used for survey.

7/2011, CCHD/SO
 #2011.015
 Found aluminum rod, down 1.6', 3'+, - south of center line of CSAH #3 and witnessed.
 4" Tamarack, N 18° E, 49.40'
 12" Cedar, S 34° W, 111.22'

8/2011, CCHD/SO
 #2011.015
 Set Mag nail from witnesses after construction, 1.5' south of new center line CSAH #3.

7/2019, CCHD/SO
 #2011.015
 Found Conc. nail, 1.5', S. of centerline CSAH #3. 1984 and 2011 witnesses are good.

7/2019, T.L. Freeman, LS 21367
 Certificate of Location, A000651792
 Filed on the above information.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Species
Diameter
Bearing
Distance

Bearing Trees, Reference Objects

Year surveyed
Location filed
Monument

By

Bearing Trees, Reference Objects

Year of search
By

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Species
Diameter
Bearing
Distance

No trees
Bearing Trees

Year surveyed
Original monument

1876
lost


Original Government Survey

Original Evidence Found

EXISTING SURVEYS

Index No. N15
T. 144 R. 25 M. 5TH Coordinates: X 2734 Y 2734
corner common to sections

CASS COUNTY LAND CORNER RECORD



Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Certificate - Jim Parker - 1985
set lost - 5/8" X 3/8" aluminum rod w/ cap
12" Balsam N 1° E 63.73'
10" Cedar S 8° E 74.90'
Doc. # 281977

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____