Index No. CASS COUNTY I	LAND CORNER RECORD
T R M Coordinates: X	
Corner common to sections	
	ISTING SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed	Year of search by
Original monument	
	= Corner
Bearing Trees	Original Bearing Trees Found
Species	Species
Diameter	Diameter
Bearing	Bearing
Distance	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed By	Year of search By
Location filed:	Location filed:
Monument:	Monument:
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	Species
Diameter	Diameter
Bearing	Bearing
Distance	Distance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed By Location filed:	Year of search By Location filed:
Monument:	Monument:
Certificate of Location of Government Corner filed in Cass County	Ву
Recorders Office as Document	Date

ndex No CASS COUNTY LAND CORNER RECORD			
R	M. Coordinates: X	Y	of
	M Coordinates: X Corner common to sections		
	Subsequent Corner Restoration	II Evidence of	Subsequent Corner Restoration Found
Year surveyed	By	Year of search	
Location filed:		Location filed:	
Monument:		Monument:	
	tion of Government Corner filed in Cass County	Ву	
Recorders Office a	as Document	Date	

Bearing Trees, Reference Objects Doruce Wilner Colimon 30" 36" 18" 19"	Species ASPEW HOSEW ELM Species ASPEW ASSEW Diameter 5" 5" 5" Bearing 588 W N538 Distance 18.0' 91.0' 35.0'
Year, of search 1972 Year, of the search 1973 Year, of the sea	Year surveyed 1908 By James Flynn Location filed Covaly Boxx 7. 5.10mp 8" OAK Monument Two 620 621 B.T.; Stump 8" OAK Monument Two 620 521 B.S.T.
Original Bearing Trees Found Species Diameter Bearing Distance	Species Aspen Inees Aspen Ouk Diameter 510 Bearing 1000 Bearing 5376 Bearing 5376 Bearing 1000 Bearing 1000 Bearing 1000 Bearing 5376 Bearing 1000 B
Original Evidence Found Year of search Monument found	i
Subsequent Corner Restoration Year surveyed 12/2000 By CCSO Location filed file #2000:036 Monument Found & located Corner	Evidence of Subsequent Corner Restoration Found Year of search By Certificate Tim Parker - 1985 Find 1'14" 1.P set s/8" x 36" a/wminum yod w/cop 24" wifine N 56° E 92.24' 7" oak \$55° E 129.15' 10" oak \$55° E 129.15' 16" Maple N 70° W 186.04' Dic. # 281978
Remonumentation certificate prepared	By