


T. 144 R. 25 M. 5th Coordinates: X _____ Y _____

NE 31 Corner common to sections 29,30,31,32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1876
Original monument Post

Original Evidence Found

Year of search 1914 by . Donner
Monument found From Gov't BTs
Survey Rec #485, Bk C, pg 547

Bearing Trees

Species	Cedar	Cedar	Cedar	Lynn
Diameter	8"	6"	6"	6"
Bearing	S 35° E	N 65° W	S 54° W	N 29° E
Distance	3 links	14 links	32 links	27 links

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 9/1914 By F.A. Donner
Location filed: Survey Record #485, Book C, page 547 and Curo Monument: Found corner set from Gov't BTs Curo Book 94, page 3 and Donner Book, page 138

Evidence of Subsequent Corner Restoration

Year of search 1935 By Hanson, CCC
Location filed: USFS Form 874-9
Monument: Forest Service location tag on post, no date, bearing or distance to corner.

Bearing Trees, Reference Objects

Species	Cedar	Spruce	_____	_____
Diameter	14"	8"	_____	_____
Bearing	N 37° W	S 70° W	_____	_____
Distance	11.9'	26.0'	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/1983 By J.R. Worcester, CCHD
Location filed: S.P. 11-603-07
Monument: Indicates corner assumed at Station 232+15.5

Evidence of Subsequent Corner Restoration Found

Year of search 8/2011 By CCHD/SO
Location filed: #2011.015
Monument: Set Mag nail from witnesses after construction, on new center line CSAH #3.

5/1984, J.H. Parker, LS 9235
Certificate of Location
Dig 8"x 15" hole, 18" deep, found spike, down 1', on center line CSAH #3 and old FS post down and rotted on N. side Rd.

7/2019, CCHD/SO #2011.015
Found Conc. nail on centerline CSAH #3. 1984 and 2011 witnesses are good.

9/1984, J.H. Parker, LS 9235
Certificate of Location
Set 5/8"x 36" aluminum rod monument with cap, down 0.3' in place of found spike and witnessed as follows:
12" Spruce, N 18° W, 95.14'
12" N. Pine, N 44° E, 109.44'
10" Elm, S 21° E, 70.08'
10" Spruce, S 35° W, 81.34'

7/2019, T.L. Freeman, LS 21367
Certificate of Location, A000651787
Filed on the above information.


7/2011, CCHD/SO #2011.015
Set P.K. from 1984 witnesses, on center line of CSAH #3 and add the following:
10" Ash, S 25° E, 80.99'

Year surveyed _____ By _____
 Location filed _____
 Monument _____
 Evidence of Subsequent Corner Restoration

Year surveyed 1914 By E.A. Danner
 Location filed Gov't Book 2, P. 547
 Monument Two Corners Set From Gov't Plots.
 Also on microfilm - roll 115 BK 99 P. 3
 Species Cedar 8" Spruce
 Diameter 14"
 Bearing N37W
 Distance 11.9'
 Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument found _____
 Original Evidence Found _____
 Existing Surveys

Year surveyed 1876
 Original monument lost
 Original Government Survey
 Species Cedar 8" Cedar 6" LYN
 Diameter 6"
 Bearing N65W
 Distance 32 LKS
 Species Cedar 8" Cedar 6" LYN
 Diameter 6"
 Bearing N65W
 Distance 32 LKS
 Subsequent Corner Restoration



Index No. V5
 CASS COUNTY LAND CORNER RECORD
 Coordinates: X _____ Y _____
 Corner common to sections NE 31, R. 45, M. 57W, T. 144N

V-5
 Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
 Certificate - Jim Parker - 1985
 End spike - set 5/8 x 36" aluminum w/ cap
 12" N. Pine N44E 109.44'
 10" Elm S21E 70.08'
 10" Spruce S35W 81.34'
 12" Spruce N18W 95.14'
 Doc. # 281972

Remuneration certificate prepared _____ By _____
 Filed at _____ Date _____