


T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
E 1/4 5 Corner common to sections 4, 5



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Tam Tam _____
Diameter 4" 4" _____
Bearing N25E S30W _____
Distance 36 LKS 9 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman
Location filed _____
Monument Set 2" x 60" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Black Spruce Tamarack Black Spruce
Diameter 7" 6" 6"
Bearing N28E N79E S50W
Distance 33.60' 20.10' 9.00'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979
Doc. # 259053

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____