


T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
N 14 21 Corner common to sections 16, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees
Species	<u>Tam Stub</u>	<u>Tam Stub</u>
Diameter	<u>6"</u>	<u>6"</u>
Bearing	<u>S3W</u>	<u>N20E</u>
Distance	<u>140 Lks</u>	<u>23 Lks</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1971 By William Okerman
Location filed _____
Monument Set 2"x40" galvanized steel pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>	<u>Tamarack</u>
Diameter	<u>6"</u>	<u>5"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N47W</u>	<u>N29E</u>	<u>S47E</u>	<u>S4W</u>
Distance	<u>14.50'</u>	<u>10.50'</u>	<u>19.40'</u>	<u>20.50'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1971 - FILED IN 1979
Doc. # 258570

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____