


T. 144 R. 26 M. 5TH Coordinates: X _____ Y _____
MC# 17 Corner common to sections 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1875
 Original monument lost

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species Br. oak Br. Oak
 Diameter 8" 6"
 Bearing N40W N45W
 Distance 235 LKS 273 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1922 By GLO
 Location filed Sec. of State
 Monument Set 2x36" I.P. w/brass cap T14N R26W
532/533
M.C.
1922

Evidence of Subsequent Corner Restoration
 Year of search 1970 By Milo Stefan
Found GLO monument in good condition.

Bearing Trees, Reference Objects
 Species Br. oak
 Diameter 16"
 Bearing N52W
 Distance 294 LKS

Bearing Trees, Reference Objects
Burr Oak
14"
N26W
200.00'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1970 - FILED IN 1979
Doc. # 246 224