


T. 144 R. 27 M. 5th Coordinates: X _____ Y _____
E 1/4 8 Corner common to sections 8, 9



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

Bearing Trees
 Species Tam Tam
 Diameter 6" 8"
 Bearing S 25 N 45 W
 Distance _____ 27 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1937 By GLO
 Location filed SEC. OF STATE
 Monument Set 1x36" I.P. w/ brass cap ¹¹⁴
58159
1937

Evidence of Subsequent Corner Restoration
 Year of search 1964 By William Okerman
 Found GLO monument in good condition.

Bearing Trees, Reference Objects
 Species Tam Tam
 Diameter 4" 6"
 Bearing S 79 E N 82 W
 Distance 38 LKS 97 LKS

Bearing Trees, Reference Objects
Tamarack Tamarack
8" 8"
N 108 W S 79 E
61.0' 25.1'
(1937 BT)

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - OKERMAN - 1964