


T. 144 R. 27 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

MC# 12 Corner common to sections 7, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Spruce</u>	<u>Cedar</u>	_____	_____
Diameter	<u>6"</u>	<u>6"</u>	_____	_____
Bearing	<u>SSW</u>	<u>SBE</u>	_____	_____
Distance	<u>18 LKS</u>	<u>31 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By GLC  
Location filed Sec. of State  
Monument Set W.C. MC. 1x36" 1/2" w/ brass cap  
WC  
MC

Evidence of Subsequent Corner Restoration

Year of search 1974 10-31 By Terry Freeman  
Found 1" iron pipe w/ brass cap left as found  
3-16-95 Cert. filed by Terry Freeman, RLS-9367  
Doc # 2465381

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Elm</u>	_____	_____
Diameter	<u>8"</u>	<u>20"</u>	_____	_____
Bearing	<u>S36 1/4 E</u>	<u>S75 3/4 W</u>	_____	_____
Distance	<u>150 LKS</u>	<u>241 LKS</u>	_____	_____

Bearing Trees, Reference Objects

<u>Cedar</u>	<u>Elm Stump</u>	<u>Ash</u>	<u>Birch</u>
<u>7"</u>	<u>20"</u>	<u>7"</u>	<u>7"</u>
<u>N69 W</u>	<u>S75 W</u>	<u>S24 W</u>	<u>S72 E</u>
<u>79.59</u>	<u>159.06</u>	<u>12.78</u>	<u>17.87</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_