


T. 144 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 12 Corner common to sections 1, 11R AND 6, 7-144-27



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

| Bearing Trees | |
|------------------------|---------------|
| Species <u>Tam</u> | <u>Tam</u> |
| Diameter <u>4"</u> | <u>3"</u> |
| Bearing <u>N20E</u> | <u>N17W</u> |
| Distance <u>15 LKS</u> | <u>20 LKS</u> |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| Bearing Trees Found | |
|---------------------|-------|
| Species _____ | _____ |
| Diameter _____ | _____ |
| Bearing _____ | _____ |
| Distance _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1937 By GLO
Location filed Sec. of State
Monument Set concrete men - 2' long 6" Dia w/brass cap
7144N
R28W R27W
S156
S12157

| Bearing Trees, Reference Objects | |
|----------------------------------|------------------|
| Species <u>W. Oak</u> | <u>W. Oak</u> |
| Diameter <u>14"</u> | <u>16"</u> |
| Bearing <u>N57E</u> | <u>S73 1/2 E</u> |
| Distance <u>73 LKS</u> | <u>86 LKS</u> |

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition.
1994, 10-31 By Terry Freeman.
Found concrete monument w/brass cap. Left
as found. 3-16-95 Cert. Filed by Terry Freeman,
RLS 21367, Doc. #365385.

| Bearing Trees, Reference Objects | |
|----------------------------------|-----------|
| W. Oak | Ash |
| 20" | 12" |
| S73 1/2 E | S65 3/4 W |
| 56.76' | 17.82' |
| (1937 BT) | (1937 BT) |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1966